



Genesee Environmental LLC
24 Industrial Park Circle
Rochester, NY 14624
Phone: (585) 247-8882
Fax: (585) 247-8884

September 28, 2016

United States Environmental Protection Agency
Region 2
290 Broadway
New York, NY 10007-1866

To Whom It May Concern:

Enclosed you will find the amended notification for the commercial project located in Utica NY, Genesee Project No. G16021.

I've included an additional copy of the notification and are requesting for you to please mark/stamp the extra copy on the front of the document as "RECEIVED", and mail back to us in the self-addressed, stamped envelope. Thank you.

Regards,



A handwritten signature in cursive script that reads 'Jamie Folwell'.

Jamie Folwell
Office Manager

U.S. EPA
NOTIFICATION OF DEMOLITION AND RENOVATION

Operator Project #	Postmark	Date Received	Notification #
I. TYPE OF NOTIFICATION (0-Original R-Revised C-Cancelled): O			
II. FACILITY INFORMATION (Identify owner, removal contractor, and other operator):			
OWNER NAME: North American Breweries			
Address 445 St. Paul Blvd.			
Address:			
City: Rochester	State: NY	Zip 14605	
Contact: Mark Brandl	Tel 585-857-4522		
REMOVAL CONTRACTOR: : Total Wrecking & Environmental, LLC			
Address: 70 Pearce			
City Tonawanda	State: NY	Zip: 14231	
Contact: Sean Reed	Tel: 716-692-2002 x-2005		
OTHER OPERATOR: Total Wrecking & Environmental, LLC			
Address: 70 Pearce			
City: Tonawanda	State: NY	Zip: 14150	
Contact: Sean Reed	Tel: 716-692-2002 x-2005		
III. TYPE OF OPERATION (D-Demo O-Ordered Demo R-Renovation E-Emer. Renovation): D			
IV. IS ASBESTOS PRESENT? (Yes/No) Yes			
V. FACILITY DESCRIPTION (Include building name, number, and floor or room number):			
Bldg. Name: Cold Block tank farm – demo of (10) 50' Tanks plus 1 story roof/walls between tanks			
Address: 445 St. Paul Blvd.			
Address:			
City: Rochester	State: NY	County: Monroe	
Site Location:			
Building Size 19600	# of Floors: 1	Age: 50+	
Present Use: Commercial	Prior Use: Commercial		
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL: Pre Demolition asbestos survey performed by Envoy Environmental Consultants, Inc. Suspect materials were sampled and analyzed by PLM and/or TEM			
VII. APPROXIMATE AMOUNT OF ASBESTOS, INCLUDING: 1. Regulated ACM to be Removed 2. Category I ACM Not Removed 3. Category II ACM Not Removed	RACM To Be Removed	Nonfriable Asbestos Material Not To Be Removed	
		Cat I	Cat II
Pipes	0		
Surface Area	0	18100	SF
Vol. RACM Debris	0		
VIII. Scheduled Dates Asbestos Removal: Start: 10/24/16		Completion: 01/31/17	
VIII. Scheduled Dates Demo/Reno: Start: 10/17/16		Completion: 01/31/17	

NOTIFICATION OF DEMOLITION AND RENOVATION (continued)

<p>X. DESCRIPTION OF PLANNED DEMOLITION/RENOVATION WORK, AND METHOD(S) TO BE USED Removal of 10 approximately 50' tall above grade storage tanks together with a 1 story roof and block walls which is built around tanks. The only ACM found was non-friable bituminous tar sealant on the underside of tanks. Tanks, roof and walls will be demolished down to top of tank bottom, and then tank bottom removed as non-friable ACM</p>		
<p>XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION AND RENOVATION SITE:</p> <p>Wet Methods</p>		
<p>XII. WASTE TRANSPORTER #1</p>		
<p>Name: M&T Trucking</p>		
<p>Address: 532 Peoria Road</p>		
<p>City: Pavillion</p>	<p>State: NY</p>	<p>Zip: 14525</p>
<p>Contact Person: Mark Cole</p>		<p>Tel: 585-509-0621</p>
<p>WASTE TRANSPORTER #2</p>		
<p>Name:</p>		
<p>Address:</p>		
<p>City:</p>		<p>Zip:</p>
<p>Contact Person:</p>		<p>Tel:</p>
<p>XIII. WASTE DISPOSAL SITE</p>		
<p>Name: Seneca Meadows</p>		
<p>Location 1786 Salcman Road</p>		
<p>City: Waterloo</p>	<p>State: NY</p>	<p>Zip: 13165</p>
<p>Telephone: 315-539-5624</p>		
<p>XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE IDENTIFY AGENCY:</p>		
<p>Name:</p>	<p>Title:</p>	
<p>Authority:</p>		
<p>Date or Order ():</p>	<p>Date Ordered to Begin ():</p>	
<p>XV. FOR EMERGENCY RENOVATIONS N/A</p>		
<p>Date and Hour of Emergency (MM/DD/YY):</p>		
<p>Description of the Sudden, Unexpected Event:</p>		
<p>Explanation of how the event caused unsafe conditions or would cause equipment damage or an unreasonable financial burden:</p>		
<p>XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR IF PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWER. Stop work. Wet and cover affected area with poly. Amend notifications, follow approved NYCRR 56 and NESHAP procedures for clean-up</p>		
<p>XVI. I CERTIFY THAN AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR PART 61, SUBPART M) WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATIN AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING NORMAL BUSINESS HOURS. (Required 1 year after promulgation)</p>		
<p> (SIGNATURE OF OWNER/OPERATOR)</p>		<p>Frank Bodami Managing Member 9/30/16 (DATE)</p>
<p>XVII. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT.</p>		
<p> (SIGNATURE OF OWNER/OPERATOR)</p>		<p>Frank Bodami Managing Member 9/30/16 (DATE)</p>



ASBESTOS CORPORATION OF AMERICA

September 30, 2010
Via Federal Express

Mr. Victor Tu
Asbestos NESHAP Coordinator
U.S. Environmental Protection Agency
Air Compliance Branch
290 Broadway
New York, New York 10007-1866

Re: Roseton Generating, LLC
Roseton Power Plant
992 River Road
Newburgh, New York 12550

Dear Mr. Tu:

This letter serves to amend the notification for the above referenced asbestos project, which was originally filed on September 26, 2016, with the following information:

Location	Quantity	Procedure	Time Frame Phase Dates
Unit 1 East Hot Reheat Line	120 square feet of pipe insulation	Wrap and Repair	10/4//16 To 10/7/16
Unit 2 CRH East Side Elevation 162'	36 square feet of pipe insulation	NYS Code Rule 56 Procedures	10/6//16 To 10/10/16
Unit 1, Basement West Hot & Cold Reheat Lines	150 square feet of debris and 80 square feet of pipe insulation		10/10//16 To 10/17/16

We trust this information satisfies the requirement for amending this notification. If you have any questions, please do not hesitate to call.

Very truly yours,

Patrick Fitzgerald
President

PF/ll
Attachment

EPAnebnebt16157



Asbestos NESHAPs Notifications
U.S. E.P.A., Air Compliance Branch
290 Broadway, 21st Floor
New York, NY 10007-1866
(212) 637-4000


NOTIFICATION OF DEMOLITION AND RENOVATION

Operator Project #1	Postmark	Date Received	Notification #
I. TYPE OF NOTIFICATION (O = Original R = Revised C = Canceled): O			
II. FACILITY INFORMATION: (identify owner, removal contractor, and other operator)			
OWNER NAME: Roseton Generating, LLC			
Address: 992 River Road			
City: Newburgh	State: New York	Zip: 12550	
Contact person: Daniel Harman	Telephone: (845)563-4905		
CONTRACTOR: Asbestos Corporation of America			
Address: 791 Nepperhan Avenue			
City: Yonkers	State: New York	Zip: 10703	
Contact person: Patrick Fitzgerald	Tel.: (914) 965-5829		
OTHER OPERATOR: N/A			
Address:			
City:	State:	Zip:	
Contact person:	Telephone:		
III. TYPE OF OPERATION: (D = Demo R = Renovation E = Emergency Renovation) E			
IV. IS ASBESTOS PRESENT? (yes/no) YES			
V. FACILITY DESCRIPTION: (Include building name, number, and floor or room number)			
Building Name: Roseton Power Plant			
Address: 992 River Road			
City: Newburgh	State: New York	Zip: 12550	
Site Location: Unit 2, Level 6, to Level 2			
Building Size: 325,000 square feet	Number of Floors: 11	Age in Years: 1974	
Present Use: Power Plant	Prior Use: Power Plant		
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:			
Independent laboratory services in accordance with all federal, state, and local regulations.			
Air Monitoring firm: Envirologic of New York, Inc., Three Neptune Road			
Poughkeepsie, New York 12601			
Lab Analysis By: Envirologic of New York, Inc., 11577			
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:			
		Non-friable asbestos material not to be removed	Indicate unit of measurement below
1. Regulated ACB to be removed	RACM to be removed	Cat I	Cat II
2. Category I ACM not removed			UNIT
3. Category II ACM not removed			
Pipes	LnFt	Ln m:	
Surface Area	1,600 Sq Ft	Sq m:	
Vol. RACM off Facility Component	CuFt	Cu m:	
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY)			
Start:	09/28/2016	Complete:	10/28/2016
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY)			
Start:	NA	Complete:	NA

Asbestos Corporation of America

Project Name: Roseton Generating, LLC, Roseton Power Plant, 992 River Road, Newburgh, NY 12550

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED: Removal and disposal of asbestos-containing debris from 1,600 square feet of floor space using NYS DOL Individual Variance Procedures.			
XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE: All procedures will be in full accordance with federal, state and local regulations.			
XII. WASTE TRANSPORTER #1 Name: Vandan Disposal, Inc. Address: 1009 Glen Cove Avenue City: Glen Head State: New York Zip: 11545 Contact Person: Mr. Vito Pesce Telephone: (718) 991-2828			
XIII. WASTE DISPOSAL SITE #1: Name: Minerva Enterprises, Inc. Address: 9000 Minerva Road, SE City: Waynesburgh State: Ohio Zip: 44688 Contact Person: Mr. Mark Stefano Telephone: (330) 866-3435			
XIII. WASTE DISPOSAL SITE #2: Name: Address: City: State: Zip: Contact Person: Telephone:			
XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE NOTIFY THE AGENCY BELOW: Name: N/A Title: Authority: Date of Order (MM/DD/YY): Date Ordered to begin (MM/DD/YY):			
XV. FOR EMERGENCY RENOVATIONS: Date and Hour of Emergency (MM/DD/YY): Description of Sudden, Unexpected Event:			
XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLED, PULVERIZED, OR REDUCED TO POWDER. Should additional asbestos be found in the immediate area that needs abatement, our containment will be enlarged to include it and we will institute all applicable work practice standards.			
XVI. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR Part 61, SUBPART M) WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING THE NORMAL BUSINESS HOURS. (Required 1 year after promulgation) <div style="text-align: right;"> Signature of Owner/Operator</div> <div style="text-align: right;">9/26/2018 (Date)</div> <div style="text-align: left;">Patrick Fitzgerald, President</div>			
XVI. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT: <div style="text-align: right;"> Signature of Owner/Operator</div> <div style="text-align: right;">9/26/2016 (Date)</div> <div style="text-align: left;">Patrick Fitzgerald, President</div>			



ASBESTOS CORPORATION OF AMERICA

September 28, 2010
Via Federal Express

Mr. Victor Tu
Asbestos NESHAP Coordinator
U.S. Environmental Protection Agency
Air Compliance Branch
290 Broadway
New York, New York 10007-1866

Re: Roseton Generating, LLC
Roseton Power Plant
992 River Road
Newburgh, New York 12550

Dear Mr. Tu:

This letter serves to amend the notification for the above referenced asbestos project, which was originally filed on September 26, 2016, with the following information:

Location	Quantity	Procedure	Time Frame Phase Dates
Unit 2 Cold Reheat Sweep at Elevation 139'	60 square feet of pipe insulation	Wrap and Repair	9/29/16 To 10/3/16

We trust this information satisfies the requirement for amending this notification. If you have any questions, please do not hesitate to call.

Very truly yours,

Patrick Fitzgerald
President

PF/II
Attachment

EPAnebnebt16157

Asbestos NESHAPs Notifications
U.S. E.P.A., Air Compliance Branch
290 Broadway, 21st Floor
New York, NY 10007-1866
(212) 637-4000

NOTIFICATION OF DEMOLITION AND RENOVATION

Operator Project #1	Postmark	Date Received	Notification #
I. TYPE OF NOTIFICATION (O = Original R = Revised C = Canceled): O			
II. FACILITY INFORMATION: (identify owner, removal contractor, and other operator)			
OWNER NAME: Roseton Generating, LLC			
Address: 992 River Road			
City: Newburgh	State: New York	Zip: 12550	
Contact person: Daniel Harman	Telephone: (845)563-4905		
CONTRACTOR: Asbestos Corporation of America			
Address: 791 Nepperhan Avenue			
City: Yonkers	State: New York	Zip: 10703	
Contact person: Patrick Fitzgerald	Tel.: (914) 965-5829		
OTHER OPERATOR: N/A			
Address:			
City:	State:	Zip:	
Contact person:	Telephone:		
III. TYPE OF OPERATION: (D = Demo R = Renovation E = Emergency Renovation) E			
IV. IS ASBESTOS PRESENT? (yes/no) YES			
V. FACILITY DESCRIPTION: (Include building name, number, and floor or room number)			
Building Name: Roseton Power Plant			
Address: 992 River Road			
City: Newburgh	State: New York	Zip: 12550	
Site Location: Unit 2, Level 6, to Level 2			
Building Size: 325,000 square feet	Number of Floors: 11	Age in Years: 1974	
Present Use: Power Plant	Prior Use: Power Plant		
VI. PROCEDURE, INCLUDING ANALYTICAL METHOD, IF APPROPRIATE, USED TO DETECT THE PRESENCE OF ASBESTOS MATERIAL:			
Independent laboratory services in accordance with all federal, state, and local regulations.			
Air Monitoring firm:	Envirologic of New York, Inc., Three Neptune Road		
	Poughkeepsie, New York 12601		
Lab Analysis By:	Envirologic of New York, Inc., 11577		
VII. APPROXIMATE AMOUNT OF ASBESTOS INCLUDING:		Non-friable asbestos material not to be removed	Indicate unit of measurement below
1. Regulated ACB to be removed	RACM to be removed	Cat I	Cat II UNIT
2. Category I ACM not removed			
3. Category II ACM not removed			
Pipes	LnFt	Ln m:	
Surface Area	1,600 Sq Ft	Sq m:	
Vol. RACM off Facility Component	CuFt	Cu m:	
VIII. SCHEDULED DATES ASBESTOS REMOVAL (MM/DD/YY)		Start: 09/28/2016	Complete: 10/28/2016
IX. SCHEDULED DATES DEMO/RENOVATION (MM/DD/YY)		Start: NA	Complete: NA

Asbestos Corporation of America

Project Name: Roseton Generating, LLC, Roseton Power Plant, 992 River Road, Newburgh, NY 12550

X. DESCRIPTION OF PLANNED DEMOLITION OR RENOVATION WORK, AND METHOD(S) TO BE USED:
Removal and disposal of asbestos-containing debris from 1,600 square feet of floor space using NYS DOL Individual Variance Procedures.

XI. DESCRIPTION OF WORK PRACTICES AND ENGINEERING CONTROLS TO BE USED TO PREVENT EMISSIONS OF ASBESTOS AT THE DEMOLITION OR RENOVATION SITE:
All procedures will be in full accordance with federal, state and local regulations.

XII. WASTE TRANSPORTER #1

Name: **Vandan Disposal, Inc.**
Address: **1009 Glen Cove Avenue**
City: **Glen Head** State: **New York** Zip: **11545**
Contact Person: **Mr. Vito Pesce** Telephone: **(718) 991-2828**

XIII. WASTE DISPOSAL SITE #1:

Name: **Minerva Enterprises, Inc.**
Address: **9000 Minerva Road, SE**
City: **Waynesburgh** State: **Ohio** Zip: **44688**
Contact Person: **Mr. Mark Stefano** Telephone: **(330) 866-3435**

XIII. WASTE DISPOSAL SITE #2:

Name:
Address:
City: State: Zip:
Contact Person: Telephone:

XIV. IF DEMOLITION ORDERED BY A GOVERNMENT AGENCY, PLEASE NOTIFY THE AGENCY BELOW:

Name: **N/A** Title:
Authority:
Date of Order (MM/DD/YY): Date Ordered to begin (MM/DD/YY):

XV. FOR EMERGENCY RENOVATIONS:

Date and Hour of Emergency (MM/DD/YY):
Description of Sudden, Unexpected Event:

XVI. DESCRIPTION OF PROCEDURES TO BE FOLLOWED IN THE EVENT THAT UNEXPECTED ASBESTOS IS FOUND OR PREVIOUSLY NONFRIABLE ASBESTOS MATERIAL BECOMES CRUMBLLED, PULVERIZED, OR REDUCED TO POWDER.

Should additional asbestos be found in the immediate area that needs abatement, our containment will be enlarged to include it and we will institute all applicable work practice standards.

XVI. I CERTIFY THAT AN INDIVIDUAL TRAINED IN THE PROVISIONS OF THIS REGULATION (40 CFR Part 61, SUBPART M) WILL BE ON-SITE DURING THE DEMOLITION OR RENOVATION AND EVIDENCE THAT THE REQUIRED TRAINING HAS BEEN ACCOMPLISHED BY THIS PERSON WILL BE AVAILABLE FOR INSPECTION DURING THE NORMAL BUSINESS HOURS.


(Required 1 year after promulgation)

Patrick Fitzgerald, President


Signature of Owner/Operator 9/26/2018
(Date)

XVI. I CERTIFY THAT THE ABOVE INFORMATION IS CORRECT:

Patrick Fitzgerald, President


Signature of Owner/Operator 9/26/2016
(Date)